Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: BRATCHER 10-3 4H

Field Name: RAGGED BUTTE Well File #: 22586

Date Incident:6/10/2017Time Incident:22:00Facility ID Number:County:MCKENZIETwp:151Rng:101Sec:15Qtr:

Location Description:

Submitted By: James Robinson Received By:

Contact Person: James Robinson

6300 BRIDGE POINT PKY, BLDG 2

SUITE 100

AUSTIN, TX 78730

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnitsOil5Gallons5Gallons5gallons

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 6/19/2017 Clean Up Concluded: 6/11/2017

Risk Evaluation:

Little risk of environmental impact due to the small quantity of release and the rapid use of micro blaze on the misted area.

Areal Extent:

Approximately 200 square yards

Potential Environmental Impacts:

Little potential environmental impact due to the small quantity of release and the rapid use of micro blaze on the misted area.

Tuesday, October 10, 2017 Page 1 of 2

Action Taken or Planned:

Shut wells down for the night and put micro blaze on the affected area. Blew down the flare line and the treater to make sure there was no residual oil in the line. Blow down the flare line prior to pigging operations.

Wastes Disposal Location: Secure Facility

Agencies Involved:

Updates

Date: 6/13/2017 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted area off location. Follow-up is required.

Date: 7/12/2017 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 7/12/2017, at 11:42am. Release was to the east of flare pit off location. Vegetation on side hill of berm has been cut and removed, area is approximately 15x40 yards. No remaining impacts seen at this time. Spoke with landowner at site, who stated that spray went much further than described in report. Was told it reached trailer to the northeast as well as the barn/shop to the east. Further follow-up required to check vegetation growth.